

FIG. 1





FIG. 2A






FIG. 2C



10/042,771

Inventor: Stuart Hall

Method & Apparatus for Displaying Help
Screen Information for Measurement Device

5/10




FIG. 2D




FIG. 3A




FIG. 3B





FIG. 3C






FIG. 5A




FIG. 5B




FIG. 5C